HAZARDOUS SUBS	TANCE RELEASE	INCIDENT R	EPORT	Incident #	
EXACT INCIDENT LOCATION NUMBER OF PERSONS REQU		Ave Bridge ent O	DATE OF INC		1 <u>02</u> 1 <u>91</u> 12:55 am pm
			TIME SPILL C	LEANED UP	<u>/3:30</u> am (b it)
HAZARDOUS SUBS INVOLVED DS1880 TAINTEN		IDENTIFYING NUMBER		TITY (LBS) BALLONS 2 <u>gallo</u> ^	R. Q. (LBS)
			90)	SUPERVISOR (1	ST LEVEL)
DRUM [RELEASE TO STORM SEWER OUTSIDE ATMOSPHERE OUTSIDE PAVEMENT OUTSIDE SOIL OTHER	SANITARY SEWEI INSIDE ATMOSPH INSIDE PAVEMEN SURFACE WATER	R	Paul Lo GENERAL SUPE	Ray
AGENCY NOTIFICATION	1 CASE #	person a Hovdo	рног 649-		ME DATE :30 7/2 :/
	NARRATIV (INCLUDE CAUS	E DESCRIPTION E AND CLEAN-U			·
CONTACT PERSON	Ty Grand		ORGN	2-4/07	PHONE <u>541-237</u>
A cardboard pa damard result from one of a Sorvices it Boei	change conforming in 12 and the cons. It	y- 1 galle yan G Sparle M	Minrox " Thinrox " all prov	bins red by	Plant Change
to spille The	waste. The	resiliary Spill, was	100%	Contain	mano;

NOTE: After completion of this form, please send a copy to the Environmental Management Group where the spill/incident took place - Plant II 19-35

HIRENV 07-02-91

PHONE

Official Use Only

INCIDENT REPORT COMPLETED BY.

Boeing Space Center (BSC) 89-18 Boeing Electron ics Center (BEC) 9E-06